

Piper PA-28-180

N2156T


Preflight Inspection

Overall




Check aircraft attitude, general condition, and any leaks under the engine compartment.

Interior




Interior



Interior



Right (Left) Wing



Right (Left) Wing Tip




**Navigation Light
Stbd (Green)
Port (Red)**


Right (Left) Wing




Right (Left) Wing



Right (Left) Wing



Right (Left) Main Gear



Nose




Windshield


Oil Dipstick

Right Cowling


Nose



Nose Gear




Nose



Temp Probe

Left Engine Cowling


Left Wing Only




Left Empennage




Empennage




Instruments




Avionics




Engine - Right Side




Engine - Bottom Right




Engine - Right




Engine - Bottom Right



Engine - Bottom Forward



Engine - Left Forward



Cabin Defrost Ducting

Cabin Air Inlet

Cabin Air Ducting

Fuel Strainer

Carb Air Heater

Engine - Left

